

DATE:

10/30/86

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

RECEIVED  
REGION VI

SUBJECT:

Potential Hazardous Waste Site

FROM:

Keith Bradley, FIT RPO  
Hazardous Waste Section (6ES-SH)

10-3 AM 8:29  
SUPERFUND BRANCH

TO:

Martha McKee, Chief  
Compliance Section (6AW-SC)

Site Name:

Farsteel Metals

Location:

Mustogee, OK

Hazsit No.:

OKD007221831

TDD No.:

OK-8410-02

A. Deliverables:

- |   |              |
|---|--------------|
| 1. Preliminary Assessment (Form 2070-2) | attached ( ) |
| 2. Site Inspection Report (Form 2070-3) | attached ( ) |
| 3. Sampling Inspection Report           | attached (X) |
| 4. Other: _____                         | attached ( ) |

B. Were drinking water wells sampled?

Yes ( ) No (X)

C. Analytical Data:

- |                         |              |
|-------------------------|--------------|
| 1. None collected       | ( )          |
| 2. Field data           | ( )          |
| 3. Contract lab results | attached (X) |
| 4. Houston lab results  | attached ( ) |

D. Comments:

Organic, inorganic and radioactive contamination has been detected in samples collected from this site.

EPA recommends additional sampling in order to document observed releases and determine if site meets rank under the HRS.

cc: (circle) Cabra 6W-E  
Gazda 6ES-E  
Taylor 6AW-HE



195913